

SERVICE BULLETIN NO. 0100

DATE: January 1, 2023

SUBJECT: Squeegee Arm Making Contact with Water Filter


Models Affected:	Serial Numbers Affected:
DX26	Not Specific

12-08-2022: Identified problem in which some models were experiencing unintentional contact between the squeegee arm, while in the upward position, and the water filter. This could potentially cause damage to the unit.

SOLUTION: Water filter component should be manually rotated into a vertical orientation, perpendicular to the floor.

Included Photo A shows water filter positioning as is.

Included Photo B shows water filter rotated downward, thereby preventing contact with the squeegee arm.



For questions and/or further information, contact:
Danny Barth, Customer & Technical Support Manager
daniel@onyxsolutions.com | (704) 992-7619 | www.onyx-solutions.com
12605 Commerce Station Drive | Suite 700 | Huntersville, NC 28078