

SERVICE BULLETIN NO. 0104

DATE: November 9, 2023

SUBJECT: Venturi Failure Risk

Models Affected:	Serial Numbers Affected:
LX-700 Series Motors	54774 - 54878

08-01-2023: Identified a problem in which the Venturi failed and became dislodged causing an interruption to the AFR. This will cause the engine to run poorly.

SOLUTION: Remove the carburetor and inspect each Venturi. If either/both are damaged/cracked, Onyx will supply replacement Venturies at no charge.



For questions and/or further information, contact:
Danny Barth, Customer & Technical Support Manager
daniel@onyxsolutions.com | (704) 992-7619 | www.onyxsolutions.com
12605 Commerce Station Drive | Suite 700 | Huntersville, NC 28078