

SERVICE BULLETIN NO. 0111

DATE: November 8, 2024

SUBJECT: Addition of Bleed Hole on Vacuum Regulator

MODELS AFFECTED: JX/TX/ZX/SX Model Machines & LX700 Engine

DOM AFTER: 10.01.24

Bleed hole - To enhance performance, all affected models will now incorporate a 0.8-millimeter bleed hole within the vacuum regulator. This addition functions as an automatic priming system, much like the system in the LX600 model. The bleed hole improves cold-start performance and promotes a stable idle by ensuring a consistent air/fuel mixture.

Bleed hole shown:



**Questions or concerns? Contact ONYX Support at
1-800-858-3533 or Support@OnyxSolutions.com**